

General Environmental Incident Summary

Incident: 4072 **Date/Time Notice:** 4/25/2016 0927 **DEM Incident No:**
Responsible Party: Site Energy Services
Date Incident: 4/22/2016 **Time Incident:** 0847 **Duration:** 0.5 minutes
County: McKenzie **Twp:** 148 **Rng:** 97 **Sec:** 17 **Qtr:**
Lat: 47.63200 **Long:** -103.07820 **Method:** Navigation quality GPS
Location Description: ONEOK Bear Creek NGL Pipeline under construction. Spill occurred where pipeline crosses 15th St. NW approximately 1 mile east of the Dunn/McKenzie County line
Submitted By: Todd Kelvington **Affiliation:** ONEOK
Address: 100 W. 5th Street
City: Tulsa **State:** OK **Zip:** 74103

Received By:

Contact Person: Eric Cothorn
2926 133rd Ave NW
Arnegard, ND 58835

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Construction Equipment Hydraulic Fluid

Description of Released Contaminant: Hydraulic Fluids

Volume Spilled: 0.25 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Unloading equipment, hydraulic line broke

Risk Evaluation:

None. Immediately cleanup occurred.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None. Immediate cleanup occurred. Based upon volume and clean up actions, no additional testing or response is planned.

Action Taken or Planned:

Spill kit immediately deployed. Impacted material immediately shoveled into bags and removed.

Wastes Disposal Location: Alexander Tervita Disposal

Agencies Involved:

Updates

Date: 4/25/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Further follow-up needed.

Date: 5/4/2016 **Status:** Inspection

Author: Washek, Sandi

Updated Volume:

Notes:

Arrived on site at 7:46 p.m. Weather was sunny, and temperature was 79 degrees F. The site is located at GPS N47.63205 W103.07823. The site is the loading and storage yard for the installation of the pipeline. Walked the site and the surrounding the cropland/road. Did not note any stained soil. No additional follow-up needed.